



Portfolio

PF201332


Auckland Art Gallery

Auckland Art Gallery has undergone a three year renovation resulting in an increase in exhibition capacity, seismic strengthening of some heritage sections; and the addition of educational, research and catering facilities.

To ensure stormwater runoff is adequately managed, designers were required to provide adequate drainage near the entrance.

As construction depth was restricted, ACO's SlabDrain, comprising 100mm deep Polycrete® channels, was selected. To complete the system, Stainless Heelsafe® Anti-Slip grates were also specified to ensure the metal surfaces would not trap women's heels.

**For more product info, visit
www.acodrain.com.au**



Product Details

Specifier: Archimedia

Product featured: SlabDrain H100K with Stainless Wedgewire Heelsafe® Anti-Slip grates

Other ACO products used in this project: Other ACO Drain trench drain systems, ACO Pipe Stainless push-fit pipe system